



# City of Aurora

## FIELD INSPECTION FORM

Date: 10-10-22

Permit #: 2019-0204 (EXPIRED) <sup>DEMO -</sup>

Address of Construction: 401 W. Springfield St. Aurora Mo 65605

Owner/Occupant: Eroylan + Joana Valdes Phone #: \_\_\_\_\_

Owner Address : 12444 Lawrence 2150, Mt Vernon Mo 65712

Contractor: \_\_\_\_\_ Phone #: \_\_\_\_\_

Contractor Address: \_\_\_\_\_

### Type of Inspection Performed

- |   |  |  |
|---|--|--|
| <input type="checkbox"/> Plan Review        | <input type="checkbox"/> Site Review             | <input type="checkbox"/> Set Back Review |
| <input type="checkbox"/> Footing            | <input type="checkbox"/> Concrete Floor/Slab     | <input type="checkbox"/> Foundation      |
| <input type="checkbox"/> Framing            | <input type="checkbox"/> Electrical              | <input type="checkbox"/> Plumbing        |
| <input type="checkbox"/> Mechanical         | <input type="checkbox"/> Final/Occupancy         | <input type="checkbox"/> Street/Alley    |
| <input type="checkbox"/> Sidewalk           | <input type="checkbox"/> Demolition              | <input type="checkbox"/> Building Safety |
| <input type="checkbox"/> Property Violation | <input type="checkbox"/> Floodplain/Flood Damage | <input type="checkbox"/> Storm Drainage  |
| <input type="checkbox"/> General Safety     | <input type="checkbox"/> Fire Safety             |  |
| <input type="checkbox"/> Other: _____       |  |  |

Notes: 1. Accessory Building Rear of Property. - Unsecured  
Entire property in floodplain - at least 90% of property in flood way.  
Severe foundation damage; water damage + deterioration to exterior  
+ interior of structure; open to elements; roof, soffit +  
facia rotted. Subfloors water damaged + rotted. Ceilings water  
damaged + rotted.

Pass \_\_\_\_\_ Rejected \_\_\_\_\_

Re-Inspect Date \_\_\_\_\_

Carrie Howlett  
Building Inspector

10/10/22  
Date/Time