



City of Aurora

FIELD INSPECTION FORM

Date: 10-10-22

Permit #: NA

Address of Construction: 100 N. McNatt Ave, Aurora Mo 65605

Owner/Occupant: Dennis Lawrence Phone #: 417-229-0965

Owner Address : 17 E Olive Street, Aurora Mo 65605

Contractor: _____ Phone #: _____

Contractor Address: _____

Type of Inspection Performed

- | | | |
|--|--|---|
| <input type="checkbox"/> Plan Review | <input type="checkbox"/> Site Review | <input type="checkbox"/> Set Back Review |
| <input type="checkbox"/> Footing | <input type="checkbox"/> Concrete Floor/Slab | <input type="checkbox"/> Foundation |
| <input type="checkbox"/> Framing | <input type="checkbox"/> Electrical | <input type="checkbox"/> Plumbing |
| <input type="checkbox"/> Mechanical | <input type="checkbox"/> Final/Occupancy | <input type="checkbox"/> Street/Alley |
| <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Demolition | <input checked="" type="checkbox"/> Building Safety |
| <input checked="" type="checkbox"/> Property Violation | <input type="checkbox"/> Floodplain/Flood Damage | <input type="checkbox"/> Storm Drainage |
| <input checked="" type="checkbox"/> General Safety | <input type="checkbox"/> Fire Safety | |
| <input type="checkbox"/> Other: _____ | | |

Notes: Southside of Building - Telephone wire / - Unsecure/Unsafe for entry. Neighboring structures collapsed. Separation + gaps in exterior. Structural gap has increased since adjacent structural collapse. Tenants account of experience during collapse indicates structural damage to floor joists + uplift of floor. Supported by visual inspection of exterior brick + walls.

Pass _____ Rejected _____

Re-Inspect Date _____

Carrie Howlett
Building Inspector

10/10/22
Date/Time