



# City of Aurora

## FIELD INSPECTION FORM

Date: 10-10-22

Permit #: NA

Address of Construction: 106 N. McNatt Ave, Aurora MO 65605

Owner/Occupant: Dennis Lawrence Phone #: 417-229-0965

Owner Address : 17 E olive St, Aurora MO 65605

Contractor: \_\_\_\_\_ Phone #: \_\_\_\_\_

Contractor Address: \_\_\_\_\_

### Type of Inspection Performed

- |  |  |   |
|--|--|---|
| <input type="checkbox"/> Plan Review                   | <input type="checkbox"/> Site Review             | <input type="checkbox"/> Set Back Review            |
| <input type="checkbox"/> Footing                       | <input type="checkbox"/> Concrete Floor/Slab     | <input type="checkbox"/> Foundation                 |
| <input type="checkbox"/> Framing                       | <input type="checkbox"/> Electrical              | <input type="checkbox"/> Plumbing                   |
| <input type="checkbox"/> Mechanical                    | <input type="checkbox"/> Final/Occupancy         | <input type="checkbox"/> Street/Alley               |
| <input type="checkbox"/> Sidewalk                      | <input type="checkbox"/> Demolition              | <input checked="" type="checkbox"/> Building Safety |
| <input checked="" type="checkbox"/> Property Violation | <input type="checkbox"/> Floodplain/Flood Damage | <input type="checkbox"/> Storm Drainage             |
| <input checked="" type="checkbox"/> General Safety     | <input type="checkbox"/> Fire Safety             |   |
| <input type="checkbox"/> Other: _____                  |  |   |

Notes: Structural integrity questionable due to adjacent shared wall structure collapse. Un safe for entry. Deterioration visible rear of structure - unsecured. Open to elements.

Pass \_\_\_\_\_ Rejected \_\_\_\_\_  
Carrie Howlett  
Building Inspector

Re-Inspect Date \_\_\_\_\_  
10/10/22  
Date/Time