



City of Aurora

FIELD INSPECTION FORM

Date: 10-10-22 Permit #: NA

Address of Construction: 110 N McNatt Ave, Aurora MO 65605

Owner/Occupant: Leonard Huse Sr, ET AL Phone #: 417-440-4381

Owner Address : 25 E Summit St, Aurora MO 65605

Contractor: _____ Phone #: _____

Contractor Address: _____

Type of Inspection Performed

- | | | |
|--|--|---|
| <input type="checkbox"/> Plan Review | <input type="checkbox"/> Site Review | <input type="checkbox"/> Set Back Review |
| <input type="checkbox"/> Footing | <input type="checkbox"/> Concrete Floor/Slab | <input type="checkbox"/> Foundation |
| <input type="checkbox"/> Framing | <input type="checkbox"/> Electrical | <input type="checkbox"/> Plumbing |
| <input type="checkbox"/> Mechanical | <input type="checkbox"/> Final/Occupancy | <input type="checkbox"/> Street/Alley |
| <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Demolition | <input checked="" type="checkbox"/> Building Safety |
| <input checked="" type="checkbox"/> Property Violation | <input type="checkbox"/> Floodplain/Flood Damage | <input type="checkbox"/> Storm Drainage |
| <input checked="" type="checkbox"/> General Safety | <input type="checkbox"/> Fire Safety | |
| <input type="checkbox"/> Other: _____ | | |

Notes: Structural integrity questionable due to adjacent shared wall structure(s). Unsafe for entry.
Deterioration visible exterior rear; separation of brick/structure. Open to elements; unsecured.

Pass _____ Rejected _____ Re-Inspect Date _____

Carrie Howlett _____ 10/10/22

Building Inspector _____ Date/Time _____